TESTING CERTIFICATE

Korea Environment & Water Works Institute

29, Yangpyung-ro 28sa-gil, Yeongdungpo-gu, Seoul, 07201, Korea Tel: +82-2-2637-1234 Fax: +82-2-2631-8767

Certificate No.: ID-201067 Page(1) / (1)Pages The end.



1. Client Name

: Waco corperation

Address

Company: 10. Nowon-ro 15-gil, Nowon-gu, Seoul Factory: 11-19. Muran 2-gil, Soheul-eup, Pocheon-si, Gyeonggi-do

2. Sample Description

Quadrangular water filter

3. Use of Report

: Quality Management

5. Date of Test

4. Sample Classification: the offered sample by client : Oct. 28, 2020. ~ Nov. 9, 2020.

6. Location of Test

: Permanent Testing Lab (29, Yangpyung-ro 28sa-gil, Yeongdungpo-gu, Seoul, Korea)

☐ On Site Testing

7. Test method used

: Available Free Residual Chlorine (ME. NO. 2019-106)

8. Testing Environment: Temperature: (Lowest 21 °C, Highest 23 °C), Humidity: (Lowest 30 % R.H., Highest 35 % R.H.)

9. Test Results

Test Item	Unit	Result			
			Out-Flow Conc.		Remark
Turbidity	NTU	5.24	0.06	98.9	-
Color	degree	15	1	93.3	
Chloroform	mg/L	0.264	0.017	93.6	

* Water Pressure: 1 kgf/cm²

Affirmation

Tested by Name

Choi Yonsu

Technical Manager Name Song Minhyung



- 1. The results shown in this test report refer only to the offered sample by client.
- 2. The test report cannot be used for the purpose of litigation or advertising, and shouldn't be republished without document approval.
- * These test results are in the scope of KS Q ISO/IEC 17025 and part of the KOLAS accreditation □Yes. ☑No.

Korea Environment & Water Works Institute

